EAST Search History

| Ref # | Hits | Search Query | DBs | Default Operator | Plurals | Time Stamp |
|----------|-------|---|---------------------------------|---------------------|---------|------------------|
| L1 | 1175 | (solder\$4 near3 (predict\$4 measur\$5 indicat\$4 meter\$4 test\$4 detect\$4 determin\$4 sens\$4 identi\$6 evaluat\$5 estimat\$5 transducer gauge cell monitor\$4 comput\$5 inspect\$5 meter calculat\$4)).clm. | US-PGPUB; USPAT; EPO; JPO | OR | ON | 2006/05/10 12:24 |
| L2 | 1 | 1 and ((fatigue crack\$5) near3 (initiat\$5 start\$4 commens\$5 creat\$5)).clm. | US-PGPUB; USPAT; EPO; JPO | OR | ON | 2006/05/10 10:40 |
| L3 | 6 | 1 and ((fatigue crack\$5) near3 (initiat\$5 start\$4 commens\$5 creat\$5)) | US-PGPUB; USPAT; EPO; JPO | OR | ON | 2006/05/10 11:19 |
| L4 | 18 | 1 and ((fatigue crack\$5 phase) near3 (initiat\$5 growth preinitiat\$5 start\$4 commens\$5 creat\$5)) | US-PGPUB; USPAT; EPO; JPO | OR | ON | 2006/05/10 12:23 |
| L5 | 3 | 1 and ((fatigue crack\$5 phase) near3 (initiat\$5 growth preinitiat\$5 start\$4 commens\$5 creat\$5)).clm. | US-PGPUB; USPAT; EPO; JPO | OR | ON | 2006/05/10 11:20 |
| L13 | 6 | 1 and fracture near3 time | US-PGPUB; USPAT; EPO; JPO | OR | ON | 2006/05/10 12:10 |
| L14 | 15886 | (solder\$4 near3 (predict\$4 measur\$5 indicat\$4 meter\$4 test\$4 detect\$4 determin\$4 sens\$4 identi\$6 evaluat\$5 estimat\$5 transducer gauge cell monitor\$4 comput\$5 inspect\$5 meter calculat\$4)) | US-PGPUB; USPAT; EPO; JPO | OR | ON . | 2006/05/10 12:04 |
| L15 | 26 | 14 and fracture near3 time | US-PGPUB; USPAT; EPO; JPO | OR | ON | 2006/05/10 12:17 |
| L16 | 2 | 15 and (\finite near3 (difference element)) | US-PGPUB; USPAT; EPO; JPO | OR | ON | 2006/05/10 12:11 |
| L17 | 2 | 15 and (finite near3 (difference element)) | US-PGPUB; USPAT; EPO; JPO | OR | ON | 2006/05/10 12:20 |
| L18 | 11168 | 14 and (fracture creep near3 analysis time) | US-PGPUB; USPAT; EPO; JPO | OR | ON | 2006/05/10 12:20 |
| L19 | 108 | 18 and (finite near3 (difference element)) | US-PGPUB; USPAT; EPO; JPO | OR | ON | 2006/05/10 12:20 |
| L20 | 48 | 14 and (fracture creep) near3 (analysis time) | US-PGPUB; USPAT; EPO; JPO | OR | ON | 2006/05/10 12:23 |

EAST Search History

| Ref # | Hits | Search Query | DBs | Default Operator | Plurals | Time Stamp |
|----------|-------|---|---|---------------------|---------|------------------|
| L21 | 7 | 20 and (finite near3 (difference element)) | US-PGPUB; USPAT; EPO; JPO | OR | ON | 2006/05/10 15:54 |
| L22 | 97771 | ((fatigue crack\$5 phase) near3 (initiat\$5 growth preinitiat\$5 start\$4 commens\$5 creat\$5)) | US-PGPUB; USPAT; EPO; JPO | OR | ON | 2006/05/10 12:23 |
| L23 | 459 | 22 and (fracture creep) near3 (analysis time) | US-PGPUB; USPAT; EPO; JPO | OR | ON | 2006/05/10 12:23 |
| L24 | 47 | 23 and (finite near3 (difference element)) | US-PGPUB; USPAT; EPO; JPO | OR | ON | 2006/05/10 12:23 |
| L25 | 47039 | 24 ((weld\$4 solder\$4) near3 (predict\$4 measur\$5 indicat\$4 meter\$4 test\$4 detect\$4 determin\$4 sens\$4 identi\$6 evaluat\$5 estimat\$5 transducer gauge cell monitor\$4 comput\$5 inspect\$5 meter calculat\$4)) | US-PGPUB; USPAT; EPO; JPO | OR | ON | 2006/05/10 12:24 |
| L26 | 3 | 24 and ((weld\$4 solder\$4) near3 (predict\$4 measur\$5 indicat\$4 meter\$4 test\$4 detect\$4 determin\$4 sens\$4 identi\$6 evaluat\$5 estimat\$5 transducer gauge cell monitor\$4 comput\$5 inspect\$5 meter calculat\$4)) | US-PGPUB; USPAT; EPO; JPO | OR | ON | 2006/05/10 14:20 |
| L27 | 2 | ("6260998").PN. | US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB | OR | OFF | 2006/05/10 14:20 |
| L37 | 743 | (73/808-815).CCLS. | US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB | OR | OFF | 2006/05/10 15:54 |
| L38 | 25 | 37 and (finite near3 (difference element)) | US-PGPUB; USPAT; EPO; JPO | OR | ON | 2006/05/10 15:54 |
| L39 | 25 | 38 and (fracture creep near3 analysis time) | US-PGPUB; USPAT; EPO; JPO | OR | ON | 2006/05/10 15:55 |